Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

GW989 NYC SCHOOL NY Spills S112141278
NW 8787 24TH AVE N/A

NW 8787 24TH AVE > 1 BROOKLYN, NY

1.299 mi.

6860 ft. Site 1 of 3 in cluster GW

 Relative:
 SPILLS:

 Higher
 Name:
 NYC SCHOOL

 Actual:
 Address:
 8787 24TH AVE

 11 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 1310765 / 2014-10-08

 Facility ID:
 1310765

 Facility Type:
 ER

 DER Facility ID:
 446623

 Site ID:
 491635

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: D4 2401 SWIS: Spill Date: 2014-02-12 Investigator: **RMPIPER** Referred To: Not reported Reported to Dept: 2014-02-13 CID: Not reported Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2014-02-13
Spill Record Last Update: 2014-10-08
Spiller Name: Not reported
Spiller Company: NYC SCHOOL
Spiller Address: Not reported

Spiller Company: 999

Contact Name: MUNENDRA SHARMA

DEC Memo: "DEC Piper spoke with Ray Lara. When Ray spoke with School this

morning, he realised a spill wasnt called in the night before. The spill occurred inside in the boiler room. No drains affected and was contained. Cleaned up the night before. The boiler room was epoxy painted and cleaned up very well. No further work recommeded by PTc. 10/8/14- DEC Piper - Based on work to date, this spill is closed. "

Remarks: "on cement - cleanup done"

All Materials:

491635 Site ID: Operable Unit ID: 1241182 Operable Unit: 01 Material ID: 2241479 Material Code: 0002A Material Name: #4 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: 20.00 Units: G

Recovered: Not reported

Map ID		MAP FINDINGS		
Direction		4		
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

Oxygenate: Not reported